

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERTL. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection:					
Company	Boyd Rhodes				
Company	Dan Guy				
OGM	Steve Demczak Environmental Scientist III				

Inspection Report

Permit Number:	C0070022			
Inspection Type:	PARTIAL			
Inspection Date:	Wednesday, December 08, 2004			
Start Date/Time:	12/8/2004 10:00:00 AM			
End Date/Time:	12/8/2004 3:00:00 PM			
Last Inspection:	Thursday, November 18, 2004			

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 30's, Snow Covered InspectionID Report Number: 491

> Accepted by: pgrubaug 12/22/2004

Permitee: SAVAGE SERVICES Operator: SAVAGE SERVICES

Site: SAVAGE COAL TERMINAL

Address: 6340 S 3000 E STE 600, SALT LAKE CITY UT 84121

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

	Total Permitted
122.28	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

Federal

State

County

Other

Types of Operations

✓ Underground □ Surface

✓ Loadout Processing Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The permittee has one permit condition - to enter the water monitoring data by using the Electronic Water Data System.

Inspector's Signature

Steve Demczak, Environmental Scientist III

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 facsimile (801) 359-3940 TIY (801) 538-7223 www.ogm.utah.gov

Date Wednesday, December 22, 2004

Inspection Continuation Sheet

Permit Number: C0070022 Inspection Type: PARTIAL

Inspection Date: Wednesday, December 08, 2004

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	\checkmark		\checkmark	
2.	Signs and Markers	V		✓	
3.	Topsoil	✓		V	
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		V	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control		V		
15.	Cessation of Operations				
16.2	Roads: Construction, Maintenance, Surfacing				
16.t	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	✓		V	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Inspection Continuation Sheet

Permit Number: C0070022 Inspection Type: PARTIAL

Inspection Date: Wednesday, December 08, 2004

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The permittee has an updated ownership and control amendment with the Division. The Division has contacted OSM using the AVS system to determine if the information accurate. It appears that the permittee has differences between the amendment and the AVS information. These changes are being worked out by OSM.

2. Signs and Markers

Identification signs were inspected and comply with the R645 Coal Rules.

3. Topsoil

The topsoil pile was moved and re-seeded last year. No vegetation has been established. There are no signs of wind or water erosion to the topsoil pile. The upper topsoil has crusted over protecting the topsoil.

4.a Hydrologic Balance: Diversions

The diversions were functioning as designed but silt has started to build-up in the ditches. The diversions are too muddy for the equipment to clean the ditches.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

I inspected the sediment ponds and no hazardous conditions were noticed. The sediment ponds did contain water but was not discharging during the inspection.

18. Support Facilities, Utility Installations

There were no new support facilities added since the last inspection.